

Date: 5 September 2023

Reference Number: SG-2309-411-H

قطاع الأجهزة والمستلزمات الطبية المركز الوطني لبلاغات الأجهزة والمستلزمات الطبية

Medical Devices Sector National Center for Medical Devices Reporting المينة المامة للضفاء والمحاودة المحاودة المحاود

رسالة سلامة Safety Communication

To: Healthcare Provide	r				إلى: مقدمي الرعاية الصحية
Title	A potential of endob	المعنوان			
Medical Device Description	Bronchofiberscope, Bronchovideoscope				اسم ووصف الجهاز/المستلزم الطبي
Medical Device Products Identifier	BF-XT40** BF-P60 BF-MP60 BF-1T60 BF-PE2 BF-TE2 BF-P150* BF-1T150		BF-H190 BF-Q190 BF-XT190 BF-1TH190 BF-260* BF-F260F* BF-1T260* scontinued	BF-6C260* BF-H290 BF-Q290 BF-1TQ290 * BF-H1100 BF-H1200 BF-1TH1200	الأرقام للجهاز/المستلزم الطبي
Manufacturer	Olympus				اسم المصنع
Authorized Representative		الممثل المعتمد			
Medical Devices Marketing Authorization (MDMA)	MDMA-1-2019-1564 MDMA-1-2019-1562 MDMA-1-2018-1065 MDMA-1-2020-1004				إذن التسويق
Potential /Associated risks	Endobronchial combustion during therapeutic procedures using lasers or argon plasma coagulation with the Olympus bronchoscope model BF Series. If endobronchial combustion occurs, patients may suffer internal burn in their airway or lungs, respiratory insufficiency, apnea, loss of consciousness, hospitalization or its prolongation, ICU care, or death.				المخاطر المحتملة/ المرتبطة بالجهاز أو المستلزم الطبي
Recommendations	To maximize patient satisfies providing the following therapy equipment: - Only Nd:YAC laser compatible lasers for compatible compa	التوصيات			

Code: MDS-F-310-020-V4



For Reporting	avoid patient injury (burns, bleeding, & perforation) or damage to the device. NCMDR	للإبلاغ
	- Never emit laser radiation before confirming that an appropriate distance between the target and the endoscope's distal end with the tip of the laser probe is in the correct position in the endoscopic image. This is essential to	
	 Do not perform laser cauterization while supplying oxygen. This may result in combustion during cauterization. This is included in the Warnings in the Operation Manual on laser cauterization with Olympus bronchoscopes. 	

Code: MDS-F-310-020-V4