

**Safety Communication**

**رسالة سلامة**

**HeartStart XL+ rotary therapy selector switch may fail**

<b>Device/ Product Description:</b>	HeartStart XL+ Defibrillator/Monitor.
<b>Brand:</b>	HeartStart XL
<b>Lot/Serial Number:</b>	Model number 861290 manufactured prior to 1 May 2017
<b>Manufacturer:</b>	Philips Healthcare
<b>Problem:</b>	<p>The Philips HeartStart XL+ Defibrillator/Monitor rotary therapy selector switch may fail, resulting in unexpected device behavior. These behaviors include:</p> <ul style="list-style-type: none"><li>• The device may not turn on</li><li>• The device may not perform the selected function</li><li>• The device may deliver a shock with an energy level different from the setting selected by the user.</li></ul>
<b>Recommendation/Actions:</b>	<ul style="list-style-type: none"><li>- Philips will contact you to arrange for repair of your unit once parts are available.</li><li>- Philips will install a replacement switch in affected devices at no charge to the customer.</li></ul> <p>For more information Please click <a href="#">here</a></p>

Devices/Products photo:



**Authorized Representative  
Details**

AR name:	<b>Philips Healthcare</b>
Assigned Contact Person:	Mohammad Alsamhan
Mobile/Phone:	0503879145
Email:	sfda.sa.met@philips.com