

<b>Safety Communication</b>		<b>رسالة سلامة</b>
<b>May Be Susceptible to Cybersecurity Vulnerability</b>		
<b>Device/ Product Description:</b>	Gemini Positron Emission Tomography/Computed Tomography Systems	
<b>Manufacturer:</b>	Philips Healthcare	
<b>Problem Summary:</b>	<p>The systems may be susceptible to a low-severity cybersecurity vulnerability. The problem is related to storage of information in a file system or device without access control, specific to removable media.</p> <p>For more information, please check <a href="#">Here</a>.</p> <p>If you think you had a problem with your device or a device your patient uses, please report the problem to SFDA through:  <a href="#">NCMDR</a>  <a href="#">Vigilance system</a>            19999 unified call center</p>	
	AR name:	Philips Healthcare Saudi Arabia Ltd.
	Name, Email and Mobile of Assigned Contact Person:	Mohammed Alsamhan Email: <a href="mailto:sfda.sa.met@philips.com">sfda.sa.met@philips.com</a> Mobile: +966 503879145
	Email and Phone of Philips KSA Customer Care Center:	Email: <a href="mailto:KSA.CCC@Philips.com">KSA.CCC@Philips.com</a> Toll Free: 8008441009 for STC 8008500468 for other providers